ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	2	Chowdeshwari Ward
Street ID	**Street Name**	**Significant Landmark**
W0276	2nd Crs	western side Kondappa Layout
Segment No.	**Total Length (m)**	
2/S-W0276/S110416	220.96	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	220.96	77.589575	13.109682	77.591596	13.109429	W0385	RAILWAY LINE

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Providing Asphalting to 26th cross western side Kondappa Layout in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	1900000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Providing Asphalting to 26th cross western side Kondappa Layout in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	002-15-000007
Work Order No.	**Work Order Date**	**Period of Extention**
EE (YNK D) E-PMT-3/WO/72/2016-17	19/05/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
19/05/2016	18/05/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
SAMBHASHIVAREDDY		0.00
Phone No.	**E-Mail ID**	
9972741359		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		DAYANANDA
Date of Inspection	**Remarks**	
17/12/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	17/12/2016	16/01/2017	COMPLETED
SE	VASU K M	17/12/2016	16/01/2017	COMPLETED
EE	VASU K M	17/12/2016	16/01/2017	COMPLETED
AEE	DEVARAJ	17/12/2016	16/01/2017	COMPLETED
AE	DAYANANDA	17/12/2016	16/01/2017	COMPLETED
AE	DAYANANDA	17/12/2016	16/01/2017	COMPLETED